

PCE Americas Inc. 711 Commerce Way Suite 8 Jupiter FL-33458 USA From outside US: +1 Tel: (561) 320-9162 Fax: (561) 320-9176

info@pce-americas.com

PCE Instruments UK Ltd.
Units 12/13
Southpoint Business Park
Ensign way
Hampshire / Southampton
United Kingdom, SO31 4RF
From outside UK: +44
Tel: (0) 2380 98703 0
Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english www.pce-instruments.com

5 K Load cell for PCE-DFG N series PCE-DFG N 5K load cell

PCE-DFG N Dynamometer series with external measuring cell and USB interface for connection to a PC

The force gauge measures both tensile and compressive forces with very high resolution. The tensile force and the compressive force are often determined in the test laboratory, for example, to determine the yield strength, the pull-off force, and the force required to actuate a push-button or switch. The force gauge is supplied with an external measuring cell. Depending on the model, the force gauge can measure up to $10,000\,N/2,248\,lbs$. Models for $1,000\,N/225\,lbs$, $2,500\,N/562\,lbs$ and $5,000\,N/1,124\,lbs$ are still available. Various eyelets or hooks with M10 or M12 thread can be adapted to the measuring cells, but your own devices with this thread can be mounted on the measuring cell.

The force gauge is equipped with a USB interface. This interface makes it possible to read the measurement data into the PC software. This makes it possible to create measurement logs and save and export them. The force gauge has a graphic LCD that displays the measured values both numerically and graphically. Furthermore, the force measuring device is protected to IP54 and can therefore also be used in harsh industrial environments, as well as train and pressure tests can be carried out outdoors in bad weather conditions easily.

Various force test stands are available for adaptation to the force gauge. The internal memory and the included hooks, extensions and tips complete the performance of this force gauge. A special feature of the PCE-DFG N force gauge is that the measuring cells are interchangeable among the models. By entering the sensitivity in mV / V, all measuring cells can be used with just one handheld device.

- USB interface
- Graphic display
- Fast response time
- PC software
- Incl. calibration
- Memory for 100 measurements
- Measuring cells easily changeable
- Incl. ISO calibration certificate

Specifications:

Measuring range 0 ... 5,000 N / 1,124 lbs

Resolution 1 N / 0.22 lbs

Accuracy ± 0.1% of the measuring range

Measurement units N, kg, lb, KPa

Display 2.8" TFT graphic display

Alarm Modes Inside, Outside, Crack, Shutdown

Sampling rate 6 ... 1600 Hz

Storage 100 measurements

Power supply NiMH battery, 6V / 1600-mAh

Battery life About 10 hours

Power adapter / charging adapter 12V / 1A

Outputs

Protection class

Operating and storage conditions

Mounting thread Measuring cell

2,500 ... 10,000 N / 562 ... 2,248 lbs

Up to 1,000 N / 225 lbs

M10 M12

IP 54

200 x 97 x 42 mm / 7.9 x 3.8 x 1.7 in

Switching output: 12V / 50-mA

-10 ... 50°C / 14 ... 122°F 5 ... 95% rh non-condensing

540 g / 1.2 lbs

Interface: USB

Delivery scope:

Dimensions Weight

1 x Dynamometer PCE-DFG N 5K

1 x Load cell

2 x Eyebolt

1 x USB cable

1 x Charger

1 x PC software

1 x User manual

1 x Calibration certificate